

JAN 0 9 2002

DIVISION OF .
OIL, GAS AND MINING

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291 Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	Como	wal Information		
1.	General Information Description Projects France (see (see (see) 1 = 6)). To (see (see) 12 = 0).			
	1.	Report Time Period: From (mo./yr.) 1 -01 To (mo./yr.) 12 - 01		
	2.	DOGM File Number (Mine No): M/043/021		
	3. Mine Name: BROWNS CANYON STONE GUARRY			
	4.	Mineral(s) Mined (or permitted to mine):		
	5.	Type of mine		
	6. Legal Description (Location of Lands Affected):			
		5(1)/4, NW1/4,1/4, Section 21, Township 15, Range 5 t		
		Www 1/4, 5w1/4,1/4, Section 21, Township 15, Range 5 E		
		1/4,1/4,1/4, Section, Township, Range		
7.	of Operator or Company: BMW STONE INC.			
	8.	Permanent Street Address: 2565 So. STATE ROAD 32		
	City, State, Zip: WANSHIP UTAH 84019			
		Phone: 820435-336-9620 Fax: 435-336-9621		
	9.	Company Representative (or designated operator):		
	,	Name: MARK WILLES		
	Title: Vice Pres, Secretary, Measur			
		Business Address: 2565 So. State Rol 3 City State Zin: Wayship 216 84017		
		City, State, 21p.		
		Phone: <u>435-336-9620</u> Fax: <u>435-336-9621</u>		
		Please check if any of the above information has changed since previous year.		
II.	<u>Minir</u>	Mining and Reclamation		
	1. Was there any mine related activity during the past year? Yes ☑ No □			
2.		If no - what was the last year of activity?		
	3.	If yes - how much ore or mineral was mined? 10,000 cube march		

4.	Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.			
	Stone is Granned as	1 0 1 -		
	Tendscape Proclects, The	he tailings are piled for		
	fecture us, tast year w	e sold helf of our tailing Pill so		
	There was no additional	ocerage disturbed upprox 15000 calic yards		
5.	5. How much additional acreage was disturbed during the past year?			
6.	 How much acreage was reclaimed during the past year? Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results. 			
7.				
	Smow came befor we	gould reclaim the tailing		
8.	What is the total disturbed acreage of entire project at years end?			
9.	Briefly summarize any mining and/or reclamation plans for the upcoming year.			
	reclaim area where tailing were stored			
NOTE:	Section III., "Additional Information" applies only to <u>large mining operations</u> .			
III. <u>Additiona</u>	l Information - R647-4-121.2 and .3			
1.	The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.			
2.	The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.			
IV. <u>Signatur</u>	<u>e Requirement</u>			
I her	eby certify that the foregoing is true	and correct.		
	Name (Typed or Print):	MARK WILLES		
	Title of Operator:	Vice Pres, Seedelay theaurer		
	Signature of Operator:	mark willer		
	Date:	1-6-02		
jb				

o:\forms\reports\MR-AR

RECEIVED

JAN 0 9 2002